

# WALKABILITY SURVEY RESULTS

Results of 2010 Chenowith neighborhood walkability study showing pedestrian conditions for streets and intersections.

Numbers in blue are numbers of vehicle crossings at the adjacent intersection. Zero figures indicate that data has not been collected for these areas.

**Conclusions/Recommendations:**

- \* Intersections need improvements
- \* Create a safe pathway that circumfrances the school grounds from Chenowith Loop to Hostetler and 6th Street to 10th Street.



## Legend

Chenowith Elementary School Grounds

## PEQI Intersections and Street Scores

- poor quality, pedestrian conditions absent
- low quality, minimal pedestrian conditions
- average quality, pedestrian quality
- high quality, some important pedestrian conditions present
- highest quality, many important pedestrian conditions present

